

State Water Resources Control Board

April 29, 2016

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8019 6675

Mr. Richard Spinale
Airport Maintenance Worker
Lincoln Regional Airport
1480 Flightline Drive
Lincoln, California 95648
rspinale@lincolnca.gov

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS
LOCATED AT LINCOLN REGIONAL AIRPORT, 1480 FLIGHTLINE DRIVE,
LINCOLN**

Dear Mr. Spinale:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on April 21, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Plot Plan – Map does not list sensor numbers and locations and the sump and tank names or numbers in CERS.	All	April 21, 2016	Ongoing	23 CCR 2711(a)(8)
2	Failure to Maintain DO Training – The training document was not signed.	All	April 21, 2016	Ongoing	23 CCR 2715(f)
3	Failure to Maintain Primary Containment – The piping sump has a bucket under the product line to catch a weeping leak. The leak needs to be repaired.	AV Gas	April 21, 2016	Ongoing	H&SC 25292(a); 23 CCR 2641(j)
4	Failure to Maintain Primary Containment – The diversion valve pit for the jet fuel system has evidence of a leak from product staining on the pea gravel. The piping sump has a bucket under the product line to catch a weeping leak. Leaks need to be repaired.	Jet Fuel	April 21, 2016	Ongoing	H&SC 25292(a); 23 CCR 2641(j)

No.	Violation	Tank	Start Date	Stop Date	Regulation
5	Failure to Maintain Testing Records On-site – Three years of testing records are required to be maintained on-site. The county inspector provided copies of the missing testing records during the inspection.	All	April 21, 2016	April 21, 2016	H&SC 25293; 23 CCR 2712(b)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Placer County Environmental Health Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Ms. Rebecca Green
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16th Floor
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

Local CUPA

Mr. Nikolay Ostrovskiy
Registered Environmental Health Specialist
Placer County Environmental Health Dept.
3091 County Center Drive
Auburn, California, 95603
nostrovs@placer.ca.gov

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: See next page.

cc: *(via email only)*

Mr. West Bourgault
Environmental Health Tech. Specialist
Placer County Environmental Health Department
wbourgau@placer.ca.gov

Mr. Nikolay Ostrovskiy
Registered Environmental Health Specialist
Placer County Environmental Health Department
nostrovs@placer.ca.gov

Mr. Anthony Lattuca
Senior Airport Maintenance
Lincoln Regional Airport
tlattuca@ci.lincoln.ca.us